

Client Name: Al Car Spares
 Client Address: Wokingham, RG41 4SP
 Equipment Make / Model: Dni-T UT528

Serial No: 822002253

Date: 11/12/25
 Engineer: Jack Burns
 Calibration Date:

Company: MTEK Solutions
 Contact: Michael Slucher
 Phone No: 07794 630655

Asset No.	Appliance Description	Location	Re-Test Date	Visual	CLASS I	CLASS I & II		Extension Leads	Pass or Fail	Notes
					Earth Bond	Insulation	Load/Earth Leakage			
							Ω	MΩ	Load	
	Floor Heater	Front Office		✓ or x			A	mA	✓ or x	✓ or x
	Walltalki charger	Front Office		✓		19.99	10	0.10		✓
	Monitor	Front Office		✓		19.99	Trans	0.10		✓
	Printer	Front Office		✓	0.14	19.99	13	0.38		✓
	Bridler Scale	Front Office		✓	0.06	19.99	13	0.41		✓
	Hyg extension Lead			✓		19.99	10	0.55		✓
	Hyg extension Lead			✓	0.18	19.99	15	0.10		✓
	Computer			X	Lim	Lim	Lim	Lim		X Basic insulation showing
	Monitor			✓	0.10	19.99	5	0.31		✓
	Net Work Splitter			✓	0.10	19.99	10	0.10		✓
	Christmas Lights			✓	Lim	Lim	Trans	Lim		✓ V5041 only
	iron			✓		19.99	5	0.10		✓
	Computer			✓	0.09	19.99	15	0.10		✓
	monitor			✓	0.05	19.99	10	0.17		✓
	Walltalki charger			✓	0.17	19.99	10	0.10		✓
	Phone charger			✓	0.10	19.99	15	0.10		✓
	Air Freshner			✓		19.99	Trans	0.10		✓
	Phone			✓		19.99	Trans	0.10		✓
	Walltalki charger			✓		19.99	Trans	0.10		✓
	Waxter machine			✓	0.10	19.99	10	0.17		✓
	clockin machine			✓		19.99	Trans	0.10		✓
	Phone charger			✓		19.99	Trans	0.10		✓

Client Name: AL Car SparesDate: 11/12/23Company: MITCH SOLUTIONSClient Address: Wokingham, RG41 4SPEngineer: Jack BurnsContact: Michael SlaterEquipment Make / Model: UN-T UT528Serial No: 822002253

Calibration Date:

Phone No: 07794 630655

Asset No.	Appliance Description	Location	Re-Test Date	Visual ✓ or x	CLASS I		CLASS I & II		Extension Leads Polarity	Pass or Fail ✓ or x	Notes
					Earth Bond Ω	Insulation MΩ	Load/Earth Leakage				
							Load A	Leakage mA	✓ or x	✓ or x	
	Laptop charger	Front office		✓		19.99	10	0.10		✓	
	Touch Pad			✓		19.99	Trans	0.11		✓	
	Monitor			✓	0.12	19.99	5	0.17		✓	
	HDMI Splitter			✓		19.99	Trans	0.10		✓	
	Phone charger			✓		19.99	Trans	0.10		✓	
	Christmas lights			✓		19.99	5	0.12		✓	
	Network Switch			✓		Lim	Lim	Lim		✓	Visual only
	Laptop charger			✓		19.99	5	0.10		✓	
	monitor			✓	0.17	19.99	10	0.19		✓	
	Phone charger			✓		19.99	Trans	0.10		✓	
	Phone charger	kitchen		✓		19.99	Trans	0.10		✓	
	Coffee machine			✓		19.99	13	0.10		✓	
	Coffee machine			✓	0.09	19.99	13	0.14		✓	
	Coffee machine			✓	0.10	19.99	13	0.10		✓	
	Fridge	middle office		✓	0.15	19.99	10	0.23		✓	
	kettle			✓	0.11	19.99	13	0.10		✓	
	Hover			✓		19.99	10	0.10		✓	
	monitor			✓	0.10	19.99	10	0.12		✓	
	monitor			✓	0.17	19.99	10	0.16		✓	
	Desk Lamp			✓							
	2g extention lead			✓	0.09	19.99	13	0.10		✓	
	monitor			✓	0.10	19.99	10	0.10		✓	

PAT Testing Logbook

Job No: 3000878

Page No: of

Your PAT Testing Was Completed by:

Client Name: Al Cor Spares

Date: 11/12/23

Client Address: Wokingham RG41 4SP

Engineer: Sarah Burns

Equipment Make / Model: UNI-T UT528

Serial No: 822002258

Calibration Date:

Company: MFCN Solutions

Contact: Michael Slaten

Phone No: 07994 630655

Asset No.	Appliance Description	Location	Re-Test Date	Visual ✓ or x	CLASS I		CLASS I & II		Extension Leads		Pass or Fail ✓ or x	Notes
					Earth Bond Ω	Insulation MΩ	Load/Earth Leakage		Polarity ✓ or x			
							Load A	Leakage mA				
	Monitor	Parade 1 st Floor office		✓	0.11	14.99	10	0.10			✓	
	monitor			✓	0.10	19.99	10	0.14			✓	
	monitor			✓	0.10	19.99	16	0.16			✓	
	Printer			✓	0.23	19.99	16	0.10			✓	
	COMPUTER			✓	0.11	19.99	10	0.10			✓	
	COMPUTER			✓	0.12	19.99	16	0.16			✓	
	COMPUTER			✓	0.10	19.99	16	0.10			✓	
	kettle			✓	0.12	19.99	13	0.10			✓	
	Floor Lamp			✓		19.99	3	0.10			✓	
	Arcade machine			✓	0.15	19.99	10	0.10			✓	
	Arcade machine			✓	0.10	19.99	10	0.10			✓	
	big extension lead			✓	0.13	19.99	13	0.10			✓	
	laptop charger			✓		19.99	5	0.10			✓	
	COMPUTER			✓	0.13	19.99	10	0.17			✓	
	Laptop Charger			✓		19.99	10	0.10			✓	
	monitor		✓	0.11	19.99	16	0.12			✓		
	Arcade machine		✓	0.21	19.99	10	0.15			✓		
	big extension lead	lower office	✓	0.10	19.99	13	0.10			✓		
	Computer		✓	0.11	19.99	5	0.17			✓		
	monitor		✓	0.10	19.99	16	0.10			✓		
	monitor		✓	0.09	19.99	10	0.19			✓		
	AC ADAPTER		✓		19.99	3	0.10			✓		

PAT Testing Logbook

 Job No: J800899

 Page No: of

Your PAT Testing Was Completed By:

 Client Name: AI Car Sales

 Date: 11/12/23

 Company: ntch solutions

 Client Address: Wokingham RG41 4EP

 Engineer: Sean Burns

 Contact: Michael Slatcher

 Equipment Make / Model: Uni-T UT528

 Serial No: 822002253

Calibration Date:

 Phone No: 07994 630655

Asset No.	Appliance Description	Location	Re-Test Date	Visual ✓ or x	CLASS I		CLASS I & II		Extension Leads Polarity	Pass or Fail ✓ or x	Notes
					Earth Bond Ω	Insulation MΩ	Load/Earth Leakage				
							Load A	Leakage mA			
					✓ or x	Ω	MΩ	A	mA	✓ or x	
	AC Adapter	Lower Office ↓		✓		19.99	3	0.10		✓	
	Monitor			✓	0.10	19.99	10	0.10		✓	
	Monitor			✓	0.10	19.99	10	0.10		✓	
	Computer			✓	0.10	19.99	16	0.10		✓	
	Monitor			✓	0.09	19.99	10	0.13		✓	
	AC adapter			✓		19.99	3	0.10		✓	
	AC adapter			✓		19.99	3	0.10		✓	
	Laminator			✓		19.99	13	0.10		✓	
	Monitor			✓	0.10	19.99	10	0.17		✓	
	Printer			✓	0.15	19.99	10	0.10		✓	
	Shredder			✓	0.10	19.99	10	0.16		✓	
	Computer			✓	0.10	19.99	10	0.10		✓	
	Computer			✓	0.11	19.99	16	0.16		✓	
	Monitor			✓	0.09	19.99	16	0.16		✓	
	Kettle			✓	0.01	19.99	13	0.10		✓	
	Computer			✓	0.09	19.99	16	0.11		✓	
	Monitor			✓	0.016	19.99	10	0.26		✓	
	Printer			✓	0.11	19.99	10	0.16		✓	
	Printer		✓	0.06	19.99	10	0.16		✓		
	Printer		✓	0.09	19.99	16	0.10		✓		
	Wester machine		✓	0.10	19.99	10	0.16		✓		
	Monitor		✓	0.10	19.99	10	0.11		✓		

PAT Testing Logbook

 Job No: JB00892

 Page No: of

Your PAT Testing Was Completed By:

 Client Name: Al car services

 Date: 1/12/23

 Client Address: Wokingham, RG41 4SP

 Engineer: Seach Burns

 Equipment Make / Model: Uni-t UTS28

 Serial No: 822002253

Calibration Date:

 Company: Mten Solutions

 Contact: Michael Skelton

 Phone No: 07994 630655

Asset No.	Appliance Description	Location	Re-Test Date	Visual ✓ or x	CLASS I		CLASS I & II		Extension Leads		Pass or Fail ✓ or x	Notes
					Earth Bond Ω	Insulation MΩ	Load/Earth Leakage		Polarity			
							Load A	Leakage mA				
	monitor	lower office		✓	0.09	19.99	10	0.11			✓	
	Phone charger			✓		19.99	Trans	0.10			✓	
	Phone charger			✓		19.99	Trans	0.10			✓	
	monitor			✓	0.07	19.99	10	0.43			✓	
	monitor			✓	0.08	19.99	10	0.40			✓	
	computer			✓	0.10	19.99	10	0.10			✓	
	computer			✓	0.10	19.99	10	0.21			✓	
	monitor			✓	0.10	19.99	10	0.17			✓	
	monitor			✓	0.10	19.99	10	0.10			✓	
	Kettle Lead			✓	0.10	19.99	10	0.10			✓	
	Christmas Lights			✓		19.99	Trans	0.10			✓	
	Christmas Tree			✓		19.99	Trans	0.10			✓	
	Computer			✓	0.10		10	0.14			✓	
	monitor			✓	0.11		10	0.55			✓	
	Phone charger			✓		19.99	Trans	0.10			✓	
	Wallw; fullw; charger			✓		19.99	Trans	0.10			✓	
	Wallw; fullw; charger			✓		19.99	Trans	0.10			✓	
	Wallw; fullw; charger			✓		19.99	Trans	0.10			✓	
	computer			✓	0.11	19.99	10	0.81			✓	
	monitor			✓	0.10	19.99	10	0.27			✓	
	Printer			✓	0.10	19.99	10	0.10			✓	
	Wallw; fullw; charger			✓		19.99	Trans	0.10			✓	

PAT Testing Logbook

 Job No: JS00898

 Page No: of

Your PAT Testing Was Completed By:

 Client Name: Al Car Sales

 Date: 11/12/25

 Client Address: Wokingham RG41 4SD

 Engineer: Jack Baras

 Equipment Make / Model: Mini UT528

 Serial No: 822002255

Calibration Date:

 Company: Mtek Solutions
 Contact: Michael Skitcar
 Phone No: 07794 630655

Asset No.	Appliance Description	Location	Re-Test Date	Visual ✓ or x	CLASS I		CLASS I & II		Extension Leads		Pass or Fail ✓ or x	Notes
					Earth Bond Ω	Insulation MΩ	Load/Earth Leakage		Polarity ✓ or x			
							Load A	Leakage mA				
	Battery charger	Lower yard		✓		19.99	45	0.10			✓	
	Battery charger			✓		19.99	45	0.10			✓	
	Battery charger			✓		19.99	45	0.10			✓	
	Battery charger			✓		19.99	45	0.10			✓	
	Phone charger			✓		19.99	Trans	0.10			✓	
	Phone charger			✓		19.99	Trans	0.10			✓	
	5y USB extension lead			✓	004	19.99	15	0.15			✓	
	Battery charger			✓		19.99	45	0.10			✓	
	5y extension lead			x	005	19.99	15	0.10			x	Very Poor condition
	Tyre machine			-	0.10	19.99	15	0.16			✓	
	Tyre machine			✓	0.15	19.99	15	0.11			✓	
	Battery charger			✓		19.99	45	0.10			✓	
	6y extension lead			x	005	19.99	15	0.10			x	Very Poor Condition
	Battery charger			✓		19.99	3	0.10			✓	
	Battery charger			✓		19.99	3	0.10			✓	
	Battery charger			✓		19.99	3	0.10			✓	
	12v charger			✓		19.99	Trans	0.10			✓	
NEW AREA NON-FERROUS												
	MICROWAVE			x	0.23	19.99	13	0.80			x	High EARTH Bond.
	Water Machine			x	0.11	19.99	13	0.10			x	Damaged cable.
	FRIDGE			✓	0.04	19.99	13	0.10			✓	

PAT Testing Logbook

 Job No: JB00898

 Page No: of

Your PAT Testing Was Completed By:

 Client Name: AI CORPUS
 Client Address: Wanhsium, R641 4SP
 Equipment Make / Model: UNIT ORSB

 Date: 11/12/23
 Engineer: Sue Burns
 Calibration Date:

 Company: Mich Solutes
 Contact: Michael Skelton
 Phone No: 07994 680655

Asset No.	Appliance Description	Location	Re-Test Date	Visual ✓ or x	CLASS I		CLASS I & II		Extension Leads Polarity ✓ or x	Pass or Fail ✓ or x	Notes
					Earth Bond Ω	Insulation MΩ	Load/Earth Leakage				
							Load A	Leakage mA			
	FLOOD LIGHT HEATER	NON-FERROUS		X		19.99	8.3	0.11		X	Insulation Showing
	Walkie-Talkie Charger			✓		19.99	13	0.10		✓	
	RADIO			✓		19.99	TRANS	0.10		✓	
	MONITOR			✓		19.99	3	0.10		✓	
	EXT LEAD			X	0.11	19.99	10	0.31		✓	
	BATTERY CHARGER			✓	0.01	19.99	13	0.11		X	Indicator Light Damaged
	Phone Charger			✓		19.99	3	0.10		✓	
	FAU			✓		19.99	3	0.10		✓	
		EBA1 STORE									
	Brew HEATER	EBA1 STORE		✓	0.02	19.99	13	0.10		✓	
	SPEAKER			✓		19.99	13	0.11		✓	
	Battery Charger			✓		19.99	TRANS	0.10		✓	
	Battery Charger			✓		19.99	3	0.10		✓	
	Battery Charger			✓		19.99	3	0.10		✓	
	Phone Charger			✓		19.99	TRANS	0.10		✓	
	4 Gong EXT LEAD		X	0.01	19.99	13	0.31		X	Damaged Cable	